Packaging Materials Included: return label, pouch with documents for U.S. Customs, box, and 1 air filled sleeve.

Lift internal flap. Place power adapter and cable into box. Close internal flap to secure accessories.

Insert device into opening of air filled sleeve.

Place air filled sleeve back into the box.

Secure box with 2" shipping tape (not provided)

Affix the return label to one side of the box.

Affix the pouch with documents for U.S. Customs on the other side of the box.

Drop your packaged device off at any FedEx Location